DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/26/2012 FORM APPROVED OMB NO. 0938-0391

NAME OF PROVIDER OR SUPPLIER JAY-RANDOLPH DEVELOPMENTAL SERVICES WINCHESTER, IN 47394 (K 000) INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification Survey conducted on 03/02/12 was conducted by the Indiana State Department of Health in accordance with 42 GFR 483-470(). Survey Date: 04/24/12 Facility Number: 19044700 Surveyor: Mark Bugni, Life Safety Code Specialist At this PSR survey, Jay-Randolph Developmental Services was found in compliance with Requirements for Participation in Medicaid, 42 CFR years and the 2000 edition of the National Fire Protection Association (N PPA) 101. Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was not sprinklered. The facility has a capacity of 6 and had a census of 6 at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using N PPA 101A, Alternative Approaches to Life Safety Code Specialist-Medical Surveyor on 04/25/12. ADDRAND REVIEW by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 04/25/12. ADDRAND REVIEW by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 04/25/12. ADDRAND REVIEW by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 04/25/12.	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) M A. BUII		PLE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED	
MARE OF PROVIDER OR SUPPLIER JAY-RANDOLPH DEVELOPMENTAL SERVICES STREET ADDRESS, CITY, STATE, ZIP CODE SAD PINEWEW IN WINCHESTER, IN 47394 DEPERTIX TAG SUMMARY STATEMENT OF DEFICIENCES (CACHI DEFICIENCY MUST BE RESCRICED BY FULL RESOLATORY OR LSC IDENTIFYING INFORMATION) (K 000) INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification Survey conducted on 0.3/02/12 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483-470(J). Survey Date: 04/24/12 Facility Number: 000948 Provider Number: 15C434 AIM Number: 100244700 Surveyor: Mark Bugni, Life Safety Code Specialist At this PSR survey, Jay-Randolph Developmental Services was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483-470(J). Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was not sprinklered. The facility has a fire alarm system with snoke detection in the corridors and common living areas. The facility has a capacity of 6 and had a census of 6 at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Code Specialist-Medical Surveyor on 04/25/12.			15G434	B. WIN	G			
PREFIX TAG REGULATORY OR LSC IDENTIFYING INFORMATION) RAPOST SURVEY REVISIT (PSR) to the Life Safety Code Recertification Survey conducted on U3/02/12 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j). Survey Date: 04/24/12 Facility Number: 000948 Provider Number: 15G434 AIM Number: 100244700 Surveyor: Mark Bugni, Life Safety Code Specialist At this PSR survey, Jay-Randolph Developmental Services was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was not sprinklered. The facility has a fire alarm system with smoke detection in the corridors and common living areas. The facility has a capacity of 6 and had a census of 6 at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Prompt with an E-score of 0.5. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 04/25/12.	NAME OF PROVIDER OR SUPPLIER				840 PINEVIEW LN		04/24/2012	
A Post Survey Revisit (PSR) to the Life Safety Code Recertification Survey conducted on 03/02/12 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j). Survey Date: 04/24/12 Facility Number: 000948 Provider Number: 156434 AlM Number: 100244700 Surveyor: Mark Bugni, Life Safety Code Specialist At this PSR survey, Jay-Randolph Developmental Services was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was not sprinklered. The facility has a fire alarm system with smoke detection in the corridors and common living areas. The facility has a capacity of 6 and had a census of 6 at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Prompt with an E-score of 0.5. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 04/25/12.	PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREF	PREFIX (EACH CORRECTIVE ACTION TAG CROSS-REFERENCED TO THE		LD BE	COMPLETION
Code Recertification Survey conducted on 03/02/12 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j). Survey Date: 04/24/12 Facility Number: 000948 Provider Number: 156434 AIM Number: 100244700 Surveyor: Mark Bugni, Life Safety Code Specialist At this PSR survey, Jay-Randolph Developmental Services was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j). Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was not sprinklered. The facility has a fire alarm system with smoke detection in the corridors and common living areas. The facility has a capacity of 6 and had a census of 6 at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the facility Prompt with an E-score of 0.5. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 04/25/12.	{K 000}	INITIAL COMMENTS		{K ()00}			
Code Specialist-Medical Surveyor on 04/25/12.		A Post Survey Revisit (PSR) to the Life Safety Code Recertification Survey conducted on 03/02/12 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.470(j). Survey Date: 04/24/12 Facility Number: 000948 Provider Number: 15G434 AIM Number: 100244700 Surveyor: Mark Bugni, Life Safety Code Specialist At this PSR survey, Jay-Randolph Developmental Services was found in compliance with Requirements for Participation in Medicaid, 42 CFR Subpart 483.470(j), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 33, Existing Residential Board and Care Occupancies. This one story facility was not sprinklered. The facility has a fire alarm system with smoke detection in the corridors and common living areas. The facility has a capacity of 6 and had a census of 6 at the time of this survey. Calculation of the Evacuation Difficulty Score (E-Score) using NFPA 101A, Alternative Approaches to Life Safety, Chapter 6, rated the						
		Code Specialist-Medi	cal Surveyor on 04/25/12.					

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/26/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUIL	JLTIPLE CONSTRUCTION DING 02		(X3) DATE SURVEY COMPLETED R 04/24/2012		
		15G434	B. WING		_			
	OVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 840 PINEVIEW LN WINCHESTER, IN 47394				
(X4) ID PREFIX TAG	X (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREFI TAG	X (EACH CORRECT CROSS-REFEREIT	S PLAN OF CORRECTION CTIVE ACTION SHOULD BE NCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE		